
ASSEMBLY INSTRUCTIONS STELLA 13



Box adapter Ground screw

Canopy

Check ring tab

Mounting screw

Hex key

Socket

Reflector disk

Mount hole

Lamp holder cover

Socket ring

DANGER - RISK OF SHOCK DISCONNECT POWER PRIOR TO INSTALLATION

- 1. Attach box adapter to junction box.
- 2. Make electrical connections per wiring diagram.
- 3. Affix canopy to the junction box/box adapter assembly with the two mounting screws provided.
- 4. Register the mount hole in the reflector disk over the three check ring tabs.
- 5. If necessary, hold reflector disk in place as you slip the cover tube over the socket and the check ring tabs.
- 6. Thread the socket ring onto the socket until the cover tube and faceplate are firmly held in place. Finger tighten only.



ASSEMBLY INSTRUCTIONS STELLA 13

TRIAC/ANALOG DIMMING BLACK HOT Light Fixture GROUND GROUND

