



1. Attach box strap and stud assembly to the junction box.

2. Make electrical connections per wiring diagram.

3. Slip center hole in light engine over stud.

4. Thread cap nut onto stud. Secure fixture by tightening cap nut.

WIRING DIAGRAM 10W TRIAC/ELV LED

TRIAC/ELV 10% Dimming







